ALARM PALM W-PLA

Alarm palm W-PLA

- Protects fabric from excessive run out.
- Alarm palms detect fabric when it tends to run off.
- Increase fabric safety operations.
- Easy to operate.
- Low maintenance.

CHARACTERISTICS

■ Two limit switches detect fabric run off levels:

- 1st level signal wired to ALARM.

- 2nd level signal wired to MACHINE STOP.

■ Alarm palms have to be installed at both Front and Back side of the machine, avoiding contact with wire, felt or fabric edges.

■ Sliding surface in stainless steel.

■ Suitable for wet or high temperature applications.

■ Max operating temperature: 100 °C or 120 °C.

ACCESSORIES

■ Electric connection box onboard.